Index

Nuclear Safety

Volume 10

The page range for each of the six issues of Vol. 10 is as follows:

No. 1, pages 1 to 118
No. 2, pages 119 to 196
No. 3, pages 197 to 286
No. 4, pages 287 to 364
No. 5, pages 365 to 482
No. 6, pages 483 to 564

A

Accelerators
  dosimetry and experience with, announcement of conference on, 299
  radiation safety, policy and practice for, 483–91
Accidents
  (see also Occurrences, Radiation accidents, and specific reactors, e.g., Reactors (fast breeder))
  analysis, 28–36, 131–43, 210–15, 300–6, 380–403
Advisory Committee on Reactor Safeguards
  chairman and vice chairman, election of, 273
  member appointment, 464
  membership, 273
Aerosols
  deposition under natural-response conditions in reactor-containment buildings, 492–98
  dispersion of radioactive in the atmosphere, research and development program on, 185, 353
  particle-size measurement of, development of new type of spectrometer for, 316
  release during fast breeder reactor accidents, 320
Air
  reaction with B_4C, 397
Air cleaning
  conferences on, 316–27
Air cleaning systems
  as an engineered safety feature in light-water-cooled power reactors, 46–52
Air–steam mixtures
  reaction with B_4C, 397
  reaction with H_2, 398–99
Airborne radioactivity
  monitoring in nuclear operations, symposium on instruments and techniques for, 54–62
Aluminum
  compatibility with $(U,Pu)O_2$, 384–85
Americium-241
  in-vivo counting in the human lung, 426–29
Aquatic life
  effect of thermal, radioactive, and chemical waste discharge into environment of, 292–98
Argon-41
  measurement in shield-cooling air discharged from reactors, portable equipment for, 316
Atmosphere
  dispersion of radioactive aerosols and gases in, research and development program on, 185, 353
  radioactivity measurement in, symposium on instruments and techniques for, 54–62
Atomic Energy Commission
  appointment of Clarence E. Larson to, 547
  appointment of Francesco Costagliola to, 105
  appointment of Theos J. Thompson to, 464
Atomic Safety and Licensing Appeal Board
  establishment of, proposal for, 272–73
Atomic Safety and Licensing Board Panel
  member appointment, 464

B

Bhabha Atomic Research Center
  air-cleaning activities, 323
Bibliographies
  of current nuclear safety literature, 563
Books
  "Code of Practice for the Protection of Persons Exposed to Ionizing Radiations in Research and Teaching", 521
  "Meteorology and Atomic Energy", 118, 185
Boral
  use as control-rod material in research reactors, review of problems with, 68–69
Boron carbide (B_4C)
  reaction with air, steam, and air–steam mixtures at high temperatures, 397
  use as control-rod material in research reactors, review of problems with, 66–67
Boron steel
  use as control-rod material in research reactors, review of problems with, 68
Brookhaven 60-in. Cyclotron
  radiation safety of, 484–85
Brookhaven Alternating Gradient Synchrotron
  radiation safety of, 486–87
Brookhaven National Laboratory
  personnel decontamination center, floor plan of, 75
Buck, John H.
  appointment to the Atomic Safety and Licensing Board Panel, 464

C

Cadmium
  use as control-rod material in research reactors, review of problems with, 64–65
Cadmium alloys (Cd–In–Ag)
  use as control-rod material in research reactors, review of problems with, 66
Cadmium alloys (Cd–Pb)
  use as control-rod material in research reactors, review of problems with, 65–66
Cambridge Nuclear Corporation
  radiation exposure incidents, 437–38, 530
Canada
  reactor-siting policies, comparison with U. S., 365–71
Chapman Division of the Crane Company
  radiographer exposure incident, 437
Chromium
  compatibility with $(U,Pu)O_2$, 384–85
Committee on Reactor Safety Technology
  organization and functions, 287–91
Computer programs
  for radiological-dose calculations, 513–20
  use in reactor-noise analysis, 501–2
CONAM Inspection, Inc.
  radiographer exposure occurrence, 346
Conferences and meetings
  (see also Seminars and Symposia)
  on accelerator dosimetry and experience, announcement of, 299
Containers
  for shipping of radioactive materials, requirements for, 332–33
  for shipping of radioactive materials, symposium on, 415–25

This index was prepared by Theodore F. Davis of AEC's Division of Technical Information Extension, Oak Ridge, Tenn.

Cornell University
explosion of plastic irradiation capsule, 252
Costagliola, Francesco
appointment to the AEC, 105
CREST
(see Committee on Reactor Safety Technology)
Curium-244
in-vivo counting in the human lung, 426–29

D

Decontamination
of persons involved in radiation accidents, design of medical unit for, 72–83
Desalting
island siting of nuclear-powered project for, 106
Duraloy Corporation
radiographer exposure incident, 346
Dysprosium
use as control-rod material in research reactors, review of problems with, 69

E

Earthquakes
study-group report on research needs, 272
Environment
monitoring of, British approach to, 504–12
Europium
use as control-rod material in research reactors, review of problems with, 69

F

Filters (air)
design, development, and cost, 320–21
design and operation of large sand-bed type at SRP, 321
development of plastic, 320
noble gas removal by, 321
performance of charged water droplets, 321
reclamation of partially plugged system at Hanford fuel processing plant, 320
testing of high efficiency, 321
Fish
effects of thermal, radioactive, and chemical wastes from nuclear power plants on, 292–98
Fissile material
packaging and transportation of, symposium on, 415–25
Fission products
behavior of gaseous in fuels, 210–15
containment in reactor accidents, work of CREST on, 291
deposition under natural-response conditions in reactor-containment buildings, model for, 492–98
Fuel-reprocessing plants
radioactivity release from, British monitoring program for, 507–8

G

Gases (radioactive)
discharge into the ground, research and development program on, 253
dispersion in the atmosphere, research and development program on, 185, 353
General Dynamics Corporation
radiography exposure incident in shipyard, 532
General Electric
status of pipe-rupture study, 217–27
Germany
reactor-siting policies, 377–79
Graphite
interaction with gases in various reactors, work of CREST on, 290–91

H

Hanauer, Stephen H.
elected chairman of ACRS, 273
Hastelloy X
compatibility with $(U,Pu)O_2$, 386
Heat exchanger
failure in HFIR, 343
Heavy section steel technology
research and development programs on, 186, 536–39
Hendrie, Joseph M.
elected vice-chairman of ACRS, 273
Hill, Hubert M.
appointment to ACRS, 464
Hot-channel factors
use in reactor-accident analysis, 28–36
Hydrogen
reaction with air–steam mixtures, 398–99
reaction with B_4C, 397
Hydrogen iodide
removal from gas streams by silver-impregnated sorbents, 322–23

I

Incinerators
dust removal from combustion gases from, 323
Incoloy 800
compatibility with $(U,Pu)O_2$, 385
Indexes
permuted title to "Nuclear Safety", 27, 227, 362, 482
Indium alloys (Cd–In–Ag)
use as control-rod material in research reactors, review of problems with, 66
Instrumentation
common mode failure of reactor control and protections systems, 38–45
for stress-wave emission studies, 9–14
Iodine (radioactive)
deposition under natural-response conditions in reactor containment buildings, model for, 492–98
design of automatic monitor for, 316
removal from gas streams by charcoal filters, 322
removal from gas streams by foams, falling water droplets, and sprays, 323
removal from gas streams by silver-impregnated sorbents, 322–23
retention on amine-containing polymers, 323
Ion-exchange columns
hazards of, 84

K

Krypton
removal from gas streams by adsorption in fluorocarbon solvents, 321
removal from gas streams by permselective membranes, 321
separation from Xe by F_2 reaction, 321

L

Labels
requirements for radioactive materials in shipment, 333–36
La Hague Center
air-cleaning activities, 323
Larson, Clarence E.
appointment to the AEC, 547
Lead alloys (Cd–Pb)
use as control-rod material in research reactors, review of problems with, 65–66
Licensing and regulations
(see also Reactors)
changes in, 116–17, 195–96, 285–86, 363–64, 478–80, 560–61
report of study group on power reactors, 547
Livermore Research and Development Laboratory
personnel decontamination center, floor plan of, 74
Lungs
in-vivo counting of transuranium nuclides in, 426–29

M

Massachusetts Institute of Technology
courses, fast nuclear power-reactor safety, 209
courses, water-cooled power reactor safety, 209
Medicine
design of decontamination units for radiation-accident victims, 72–83
Metals and Controls, Incorporated
radiation exposure incident, 251
Meteorology
aerodynamic effects of the EBR-II reactor complex on effluent concentration, 228–42
book, "Meteorology and Atomic Energy", 118
training of reactor-operating staff in local conditions of, 431–36
Methyl iodide
removal from gas streams by charcoal filters, 322
removal from gas streams by foams, falling water droplets, and sprays, 323
Missiles
generation and protection from during accidents in light-water-cooled reactors, 300–6
Molybdenum
compatibility with $(U,Pu)O_2$, 386
Monitoring
of airborne radioactivity, symposium on instruments and techniques for, 54–62

N

National Bureau of Standards Linear Accelerator
radiation safety of, 484–86
Niobium
compatibility with $(U,Pu)O_2$, 384–86
Noble gases
removal from gas streams, 321
Nuclear facilities
monitoring of airborne radioactivity from, symposium on instruments and techniques for, 54–62

"Nuclear Safety"
permuted-title index to, 27, 227, 362, 482
Nuclear Safety Information Center
availability of operating-experience articles from, 354, 441
bibliographies of current nuclear safety literature, 563
selective dissemination of information program for operating organizations, 354, 442, 543–44, 563
state-of-the-art reports, 481, 562
NUMEC
plutonium drum leakage incident, 530–31

O

Oak Ridge Isochronous Cyclotron
radiation safety of, 485
Oak Ridge National Laboratory
personnel decontamination center, floor plan of, 77
Occurrences
Babcock and Wilcox Test Reactor, 251, 532–33
Big Rock Point Reactor, 438–39, 531
Cambridge Nuclear Corporation, 437–38, 530
Chapman Division of the Crane Company, 437
Conam Inspection, Inc., 346
Connecticut Yankee Reactor, 344–45, 351–52, 438, 533
Cornell University TRIGA Reactor, 343–44
Duraloy Corporation, 346
Elk River Reactor, 438
General Dynamics Corp., 532
Gulf General Atomic TRIGA Mark F, 532
High Flux Isotope Reactor, 343
Humboldt Bay Reactor, 345–46
Indian Point 1 Reactor, 344, 531
La Crosse Reactor, 251
Lucens Experimental Nuclear Power Station, 437
Metals and Controls, Inc., 251
Northrop Corporation TRIGA Reactor, 533–34
N. S. Savannah Reactor, 344
Indian Point Reactor, 531
NUMEC, 530–31
Rocky Flats Plant, 437
San Onofre Reactor, 252–53
Shippingport Reactor, 345
Texas A & M TRIGA Reactor, 532
TRIGA Reactors, 437
University of Missouri Research Reactor, 440
University of Washington Educator Reactor, 250–51
U. S. Geological Surveys TRIGA Reactor, 436
Virginia Polytechnic Institute Research Reactor, 345

P

Particles
size determination in aerosols, development of spectrometer for, 316
Plutonium-238
in-vivo counting in the human lung, 426–29
Plutonium-239
in-vivo counting in the human lung, 426–29
Plutonium oxide systems ($(U,Pu)O_2$)
irradiation performance with various claddings, 380–89
Potassium
compatibility with $(U,Pu)O_2$, 385
Power plants
(see also Reactors (power), and specific power reactors, e.g., Reactors (Big Rock Point))
siting of nuclear and fossil fueled, study-group report on, 271–72

R

Radiation accidents
medical unit for handling contaminated persons from, design of, 72–83
Radiation detectors
for airborne radioactivity, symposium on, 54–62
Radiation dose
from reactor accidents, survey of computer programs for calculating, 513–20
Radiation exposure
of ^{131}I processors, 437–38
of radiographer, 346, 437
of X-ray diffractometer operator, 251
in uranium mines, regulations on, 272
Radiation monitoring
environmental, British approach to, 504–12
Radiation protection
in research and teaching activities, book on, 521
Radiation safety
policy and practive for accelerators, 483–91
Radioactive materials
labeling requirements, 333–36
packaging and transportation of, symposium on, 415–25
transportation regulations for, 329–36
Radioactive wastes
environmental monitoring of, British approach to, 504–12
treatment and disposal, progress summary of research and development projects on, 184–85, 352–54, 539–43
Radioactivity
monitoring of airborne, symposium on instruments and techniques for, 54–62
Radiography
radiation exposure occurrences, 346, 437, 532
Radioisotopes
packaging and transportation of, symposium on, 415–25
Ramey, James T.
five-year prognosis of regulation program, 105–6
Reactor containment
air-cleaning systems for light-water-cooled power reactors, 46–52
fission-product deposition under natural-response conditions, model for calculating, 492–98
testing of systems used in light-water-cooled reactors, 308–15
Reactor control
use of reactivity-balance monitor as an anomaly detector, 411–14
Reactor control rods
materials for research reactors, review of problems with, 63–70
Reactor control systems
common mode failure of control and protection devices, 38–45
work of CREST on, 291
Reactor coolants
hot-channel factors in, computation and use of in accident analysis, 28–36
Reactor cores
workshop on analysis techniques and criteria, 482
Reactor fuel pins ($(U,Pu)O_2$)
compatibility with various cladding materials, 384–86
fission-gas release from, 381–84
irradiation performance, 380–89
irradiation swelling of, 381–84
transient behavior, 386–89
Reactor fuel pins (UO_2)(stainless steel clad)
reaction with high-temperature steam, 396–97
Reactor fuel pins (UO_2)(Zircaloy clad)
reaction with high-temperature steam, 392–96
Reactor fuels
transportation, research and development projects on safety of, 353
Reactor fuels (UO_2)
fission-gas behavior in, 210–15
Reactor operators
role of simulators in determining licensing eligibility for, 250
selection and certification for fast-burst reactors, 374–75
training with computerized simulators, 405–10
training in local meteorology, 431–36
Reactor pipes
status report on rupture study at General Electric, 217–27
Reactor pressure vessels
incipient failures in, detection by stress-wave emissions, 4–17
initiation and propagation of cracks in steel, work of CREST on, 290
irradiation effects on heavy-section steels, 535–36
safety of prestressed concrete, work of CREST on, 291
Reactor safety
analysis of supplementary information requested during licensing, 197–209
common mode failure considerations in the design of systems for protection and control, 38–45
computer handling of data on, 186
courses, 118, 209, 564
evaluation of fast-burst reactors, 372–76
progress summary of research and development projects for fast reactors, 179–82, 348–52
progress summary of research and development projects for gas-cooled reactors, 182–84, 352
progress summary of research and development projects for water-cooled reactors, 85–105, 254–71, 343–63
review for fast reactors, 19–27
work of CREST on, 287–91
Reactor simulators
role in determining licensing elibibility for reactor operators, 250
use in training reactor operators, 494–10
Reactor siting
comparison of Canada and U. S. policies on, 365–71
German policies on, 377–79
safety considerations for fast-burst reactors, 375

study-group report on, 271–72
Reactors
accident analysis, computation and use of hot-channel factors in, 28–36
incidents at ORNL, simultaneous failure in control and protection systems, 40–41
monitoring of airborne radioactivity from, symposium on instruments and techniques for, 54–62
new technical-specification system adopted for, 249
noise analysis, Japan–U. S. seminar on, 499–503
operating experience, availability of report series on, 441
operating experience, NSIC selective dissemination of information on, 442
Reactors (ASTR)
use of Cd as control-rod material, review of problems with, 64
Reactors (Babcock and Wilcox Test)
failure of recirculation header, 251
Reactors (Bell)
floor plan of, 80
licensing and regulation, 110, 190, 276, 356, 468, 551–52
Reactors (Beaver Valley)
licensing and regulation, 274, 276, 356, 468, 552
Reactors (Big Rock Point)
addition of control-rod-drive thimble supports, 253
centerline melting of fuel rods, 438–39
fuel failure, 531
licensing and regulation, 113, 193, 280, 360, 472, 556
Reactors (Bolsa Island 1)
licensing and regulation, 110
Reactors (Bolsa Island 2)
licensing and regulation, 110
Reactors (BONUS)
licensing and regulation, 113, 193, 280, 360, 472, 556
use of B–SS as control-rod material, review of problems with, 68
Reactors (Brookhaven Graphite)
use of B–SS as control-rod material, review of problems with, 68
Reactors (Browns Ferry 1)
licensing and regulation, 110, 190, 276, 356, 468, 552
Reactors (Browns Ferry 2)
licensing and regulation, 110, 190, 276, 356, 468, 552
Reactors (Browns Ferry 3)
licensing and regulation, 110, 190, 276, 356, 468, 552
Reactors (Brunswick 1)
licensing and regulation, 110, 190, 276, 356, 467–68, 473, 551–52
Reactors (Brunswick 2)
licensing and regulation, 110, 190, 276, 356, 467–68, 473, 551–52
Reactors (BSR)
use of B_4C as control-rod material, review of problems with, 66–67
use of Cd–Pb alloy as control-rod material, review of problems with, 65–66
Reactors (Calvert Cliffs 1)
licensing and regulation, 110, 190, 276, 355–56, 468, 473, 551–52, 557
Reactors (Calvert Cliffs 2)
licensing and regulation, 110, 190, 276, 468, 473, 551–52, 557
Reactors (Connecticut Yankee)
licensing and regulation, 108, 113, 193, 274, 280, 355–56, 360, 472, 556
loss of off-site power, 533
power-distribution measurements, diesel-generator failures, and spurious scrams, 251–52
power uprating, stuck rod, xenon transient and diesel-loading quirk, 438
scram caused by inverters, 344
scram caused by turbine oil pressure, 344–45
tests on control-rod-induced flux tilt, 345
Reactors (Cook 1)
licensing and regulation, 110, 190, 274–76, 356, 468, 552
Reactors (Cook 2)
licensing and regulation, 110, 190, 274–76, 356, 468, 552
Reactors (Cooper)
licensing and regulation, 110, 190, 276, 356, 468, 552
Reactors (Cornell University TRIGA)
common failure mode in scram circuit, 343–44
Reactors (Crystal River 3)
licensing and regulation, 108, 110, 190, 276, 356, 468, 552
Reactors (CVTR)
licensing and regulation, 113, 193, 280, 360, 472, 556
Reactors (Diablo Canyon 1)
licensing and regulation, 110, 190, 276, 356, 468, 552
Reactors (Diable Canyon 2)
licensing and regulation, 110, 190, 276, 356, 468, 552
Reactors (Dresden 1)
licensing and regulation, 113, 193, 280, 360, 472, 556
use of B–SS as control-rod material, review of problems with, 68
Reactors (Dresden 2)
licensing and regulation, 110, 190, 276, 356, 468, 552
use of B–SS as control-rod material, review of problems with, 68
Reactors (Dresden 3)
licensing and regulation, 110, 190, 276, 356, 468, 552
Reactors (Duane Arnold)
licensing and regulation, 188, 190, 276, 356, 468, 552
Reactors (Easton)
licensing and regulation, 108–10
Reactors (EBR-II)
aerodynamic effects of building complex on effluent concentration released from, 228–42
licensing and regulation, 113, 193, 280, 360, 472, 556
Reactors (EBWR)
licensing and regulation, 113, 193, 280, 360, 472, 556
Reactors (Elk River)
licensing and regulation, 113, 193, 280, 360, 472, 556
primary steam and feedwater pipe weldments, defects and cracks in, 438
use of B–SS as control-rod material, review of problems with, 68
Reactors (fast)
design and safety features, 19–27
safety of, progress summary of research and development projects on, 179–82, 348–52, 544–46
Reactors (fast breeder)
accidents, release of Pu aerosols during, 320
Reactors (fast-burst)
accident analysis, 375–76
experiments, effects on safety of, 376
operating characteristics of, 372
operating personnel, selection and certification of, 374–75
safety evaluation of, 372–76
siting of, 375
Reactors (Fermi 1)
licensing and regulation, 113, 193, 280, 360, 472, 556
Reactors (Fermi 2)
licensing and regulation, 468, 473, 552
Reactors (Fitzpatrick)
licensing and regulation, 275–76, 356, 469, 553
Reactors (FNR)
use of B_4C as control-rod material, review of problems with, 66–67
use of B–SS as control-rod material, review of problems with, 68
Reactors (Fort Calhoun)
licensing and regulation, 110, 190, 275, 277, 281, 357, 469, 553
Reactors (Fort St. Vrain)
licensing and regulation, 109–10, 190, 277, 357, 469, 553
Reactors (gas cooled)
safety of, progress summary of research and development projects on, 182–84, 352, 546
Reactors (Ginna)
licensing and regulation, 111, 190, 277, 357, 469, 473–74, 553, 557
Reactors (Gulf General Atomic TRIGA Mark F)
transient fuel-follower rod failure, 532
Reactors (Hatch)
licensing and regulation, 111, 190, 277, 357, 469, 474–75, 553
Reactors (HFBR)
use of Dy as control-rod material, review of problems with, 69
Reactors (HFIR)
heat-exchanger tube failures, 343
personnel decontamination center, floor plan of, 78
use of Dy as control-rod material, review of problems with, 69
Reactors (High Flux)
contamination occurrence, 252
Reactors (Humboldt Bay)
licensing and regulation, 109, 113, 193, 280, 360–61, 472, 556
Reactors (Humboldt Bay 3)
core flow overestimation, 345
loss of on-site and off-site power, 345–46
Reactors (Hutchinson Island 1)
licensing and regulation, 357, 361, 469, 553
Reactors (HWCTR)
use of B–SS as control-rod material, review of problems with, 68
Reactors (Indian Point 1)
isolation-valve motor failure, 344
licensing and regulation, 113, 193, 280, 360, 472, 556
use of B–SS as control-rod material, review of problems with, 68
Reactors (Indian Point 2)
licensing and regulation, 111, 191, 277, 357, 469, 553
siting criteria, comparison with Canadian Pickering station, 365–71
Reactors (Indian Point 3)
licensing and regulation, 111, 191, 277, 281–82, 357, 361, 469, 476, 553

Reactors (Indian Point 4)
licensing and regulation, 553, 557
Reactors (Indian Point 5)
licensing and regulation, 553, 557
Reactors (Kewaunee)
licensing and regulation, 109, 111, 191, 277, 357, 469, 553
Reactors (La Crosse)
failures in swaged tubing fittings, 344
feedwater-control problems, 344
ion-chamber sensitivity to control-rod position, 344
licensing and regulation, 113, 193, 280, 282, 360, 472, 556
reactivity descrepancy, 344
water level in, error in indication of, 251
Reactors (light-water cooled)
accidents, protection from missiles generated in, 300–6
air-cleaning systems as an engineered safety feature, 46–52
loss-of-coolant accidents, work of CREST on, 289–90
metal–water reactions during nuclear excursion and loss-of-coolant accidents, 392–402
protection from missiles generated in during accidents, 300–6
testing of containment systems for, 308–15
Reactors (liquid-sodium cooled)
effects of pressure waves on structural components of, work of CREST on, 290
Reactors (LMFBR)
development, issuance of comprehensive plan for, 106–7
Reactors (LPR)
use of B_4C as control-rod material, review of problems with, 66–67
Reactors (Lucens Experimental Nuclear Power Station)
loss-of-coolant incident, 437
Reactors (Maine Yankee)
licensing and regulation, 111, 189, 191, 277, 357, 469, 553
Reactors (Malibu)
licensing and regulation, 111, 191, 277, 357, 469, 553
Reactors (Midland 1)
licensing and regulation, 277, 282, 357, 469, 476, 553
Reactors (Midland 2)
licensing and regulation, 277, 282, 357, 469, 476, 553
Reactors (Millstone Point 1)
licensing and regulation, 111, 191, 277, 357, 469, 553
Reactors (Millstone Point 2)
licensing and regulation, 357, 361, 469, 553
Reactors (MITR)
use of Cd as control-rod material, review of problems with, 65
Reactors (Monticello)
floor plan of, 81
licensing and regulation, 111, 189, 191, 277, 357, 469, 553, 557
Reactors (MTR)
use of Cd as control-rod material, review of problems with, 64–65
Reactors (New Production)
licensing and regulation, 193, 472
Reactors (Nine Mile Point)
licensing and regulation, 111, 191, 277, 357, 470, 476–77, 554
Reactors (North Anna 1)
licensing and regulation, 470, 477, 554
Reactors (North Anna 2)
licensing and regulation, 477, 554
Reactors (Northrop Corporation TRIGA)
common failure mode, 533–34
Reactors (NRR)
use of B_4C as control-rod material, review of problems with, 66–67
Reactors (N. S. Savannah)
control-rod-drive failure, 344
licensing and regulation, 115, 193, 472
operating license, 242
Reactors (Oconee 1)
floor plan of, 79
licensing and regulation, 111, 191, 277, 358, 470, 554
Reactors (Oconee 2)
floor plan of, 79
licensing and regulation, 111, 191, 277, 358, 470, 554
Reactors (Oconee 3)
licensing and regulation, 111, 191, 277, 358, 470, 554
Reactors (ORNL Graphite)
use of B–SS as control-rod material, review of problems with, 68
Reactors (organic-cooled)
effects of pressure waves on structural components of, work of CREST on, 290
Reactors (ORR)
use of Cd as control-rod material, review of problems with, 64–65
Reactors (Oyster Creek)
siting criteria, comparison with Canadian Pickering station, 365–71
Reactors (Oyster Creek 1)
licensing and regulation, 111, 114, 191, 278, 282–83, 358, 470, 477, 554, 557
Reactors (Oyster Creek 2)
licensing and regulation, 111, 191, 278, 357, 361
Reactors (Palisades)
licensing and regulation, 111, 191, 278, 358, 470, 554
Reactors (Pathfinder)
licensing and regulation, 114, 189, 193, 472
use of B–SS as control-rod material, review of problems with, 68
Reactors (PBR)
use of Cd as control-rod material, review of problems with, 65
Reactors (Peach Bottom)
personnel decontamination center, 82
Reactors (Peach Bottom 1)
licensing and regulation, 193, 472
Reactors (Peach Bottom 2)
licensing and regulation, 111, 191, 278, 358, 470, 554
Reactors (Peach Bottom 3)
licensing and regulation, 111, 191, 278, 358, 470, 554
Reactors (Pickering)
siting criteria, comparison with Indian Point and Oyster Creek stations, 365–71
Reactors (Pilgrim)
licensing and regulation, 111, 114, 191, 278, 358, 470, 554
Reactors (Piqua)
licensing and regulation, 193, 472
Reactors (Plum Brook)
containment penetrations, experience with, 243–48
Reactors (Point Beach 1)
licensing and regulation, 111, 191, 278, 358, 470, 554
Reactors (Point Beach 2)
licensing and regulation, 111, 191, 278, 358, 470, 554
Reactors (pool type)
power-uprating experience following conversion from plate-type to TRIGA fuel elements, 522–29
Reactors (power)
air-cleaning activities, 324
analysis of supplementary information requested during licensing, 197–209
effects of thermal, radioactive, and chemical wastes on aquatic communities, 292–98
operator training with computerized simulators, 405–10
radioactivity release from, British monitoring program for, 508
siting, study-group report on, 271–72
Reactors (Prairie Island 1)
licensing and regulation, 112, 191, 278, 358, 470, 554
Reactors (Prairie Island 2)
licensing and regulation, 112, 191, 278, 358, 470, 554
Reactors (pulse)
control and safety of, corrections to article in "Nuclear Safety, Vol. 9, No. 5, 284
Reactors (PULSTAR)
use of Cd–In–Ag alloy as control-rod material, review of problems with, 66
Reactors (Quad Cities 1)
licensing and regulation, 112, 192, 278, 358, 470, 554
Reactors (Quad Cities 2)
licensing and regulation, 112, 192, 278, 358, 470, 554
Reactors (Rancho Seco)
licensing and regulation, 112, 189, 192, 278, 358, 470, 554
Reactors (research)
control-rod materials, review of problems with, 63–70
Reactors (Robinson 2)
licensing and regulation, 112, 192, 278, 358, 470, 554
Reactors (Russellville)
licensing and regulation, 112, 114, 192, 278, 283, 358, 470, 554
Reactors (Salem 1)
licensing and regulation, 112, 114, 192, 278, 358, 470, 554
Reactors (Salem 2)
licensing and regulations, 112, 114, 192, 278, 358, 470, 554
Reactors (San Onofre)
licensing and regulation, 193, 472
steam-generator thermal-power imbalance, 252–53
Reactors (Saxton)
licensing and regulation, 193, 283, 472
Reactors (Seabrook)
licensing and regulation, 471, 477, 555
Reactors (SEFOR)
licensing and regulation, 112, 189, 192, 278, 358, 361–62, 471, 555
Reactors (Sequoyah 1)
licensing and regulation, 192, 194, 279, 359, 471, 555
Reactors (Sequoyah 2)
licensing and regulation, 279, 359, 471, 555
Reactors (SER)
use of Cd–In–Ag alloy as control-rod material, review of problems with, 66
Reactors (Shippingport)
ion-chamber sensitivity, effect of polyethylene wrapping on, 345
Reactors (Shippingport Core 2)
licensing and regulation, 472

Reactors (Shoreham)
licensing and regulation, 112, 192, 279, 283, 359, 471, 555
Reactors (SM-1)
use of Eu as control-rod material, review of problems with, 69
Reactors (SRE)
licensing and regulation, 193, 472
Reactors (Surry 1)
licensing and regulation, 112, 192, 279, 359, 471, 555, 557–58
Reactors (Surry 2)
licensing and regulation, 112, 192, 279, 359, 471, 555, 557–58
Reactors (Texas A & M)
power-uprating experience following conversion from plate-type to TRIGA fuel elements, 522–29
startup incident, 532
Reactors (Three Mile Island 1)
licensing and regulation, 112, 192, 279, 359, 471, 555
Reactors (Three Mile Island 2)
licensing and regulation, 362, 471, 555, 558–59
Reactors (TRIGA)
control-rod-drive problems, 437
Reactors (Trojan)
licensing and regulation, 555, 559
Reactors (Turkey Point 3)
licensing and regulation, 112, 115, 192, 279, 359, 471, 555
Reactors (Turkey Point 4)
licensing and regulation, 112, 115, 192, 279, 359, 471, 555
Reactors (UMRR)
use of B_4C as control-rod material, review of problems with, 66–67
Reactors (U. S. Geological Survey's TRIGA)
decrease in fuel-element temperature during steady-state full-power operation of, 436
Reactors (University of Florida Research)
misplacement of ^{235}U, 343
Reactors (University of Kansas)
use of boral as control-rod material, review of problems with, 68
Reactors (University of Missouri, Columbia)
use of boral as control-rod material, review of problems with, 68
Reactors (University of Missouri Research)
anomalous increase in power level of, 440
startup and operating experiences, 337–46
Reactors (University of Washington Educator)
reactivity occurrence, 250–51
Reactors (UVR)
use of B_4C as control-rod material, review of problems with, 66–67
Reactors (Vermont Yankee)
licensing and regulation, 112, 192, 279, 359, 471, 555
Reactors (VESR)
licensing and regulation, 193, 472
Reactors (Virginia Polytechnic Institute Research)
ion-chamber sensitivity, effect of polyethylene wrapping on, 345
Reactors (water cooled)
effects of pressure waves on structural components of, work of CREST on, 290
safety of, progress summary of research and development projects on, 85–105, 254–71, 343–63, 535–39
Reactors (WTR)
use of Cd as control-rod material, review of problems with, 65
Reactors (Yankee)
licensing and regulation, 193, 472
Reactors (Zion 1)
licensing and regulation, 112, 192, 194, 279, 283, 359, 471, 555
Reactors (Zion 2)
licensing and regulation, 112, 192, 194, 279, 283, 359, 471, 555
Regulation and licensing
changes in, 478–80
Regulations
changes in, 116–17, 195–96, 285–86, 363–64, 478–80
five-year prognostication by Commissioner Ramey, 105–6
for packaging and transportation of radioactive materials, symposium on, 415–25
Reports (state-of-the-art)
of NSIC, 481
Rhenium
compatibility with $(U,Pu)O_2$, 386
Rhenium alloys (Re–W)
compatibility with $(U,Pu)O_2$, 386
Rocky Flats Plant
plutonium fire, 437

S

Sampling
of airborne radioactivity, symposium on, 54–62
Savannah River Plant
air-cleaning activities, 324
Seminars (Japan–U. S.)
on reactor-noise analysis, 499–503
Ships (nuclear)
radioactivity release from, British monitoring program for, 509
Silver alloys (Cd–In–Ag)
use as control-rod material in research reactors, review of problems with, 66
Sodium
compatibility with $(U,Pu)O_2$, 384–85
Spectrometers
development of new type for particle-size measurements in aerosols, 316
Stack disposal
from EBR-II, aerodynamic effects of buildings on, 227–42
Stainless steel
reaction with high-temperature steam, 396–97
Stainless steel (18-8-1)
compatibility with $(U,Pu)O_2$, 385
Stainless steel (304)
compatibility with $(U,Pu)O_2$, 385
use as reactor piping, status report on rupture studies at General Electric, 217–27
Stainless steel (316)
compatibility with $(U,Pu)O_2$, 385–86
Stainless steel (347)
compatibility with $(U,Pu)O_2$, 386
Stainless steel (austenitic)
compatibility with $(U,Pu)O_2$, 384–85
Stainless steel–UO_2 aerosols
removal from gas streams by filtration, effect of heat and moisture on, 321
Stanford Linear Accelerator
radiation safety of, 487
Steam
reaction with B_4C, 397
reaction with metals during reactor accidents, 392–402
Steam–air mixtures
reaction with B_4C, 397
reaction with H_2, 398–99
Steam electric plants
siting of nuclear and fossil fueled, study-group report on, 271–72
Steel (ASTM A-106B)
use as reactor piping, status report on rupture studies at General Electric, 217–27
Steel (ASTM A-335-P22)
use as reactor piping, status report on rupture studies at General Electric, 217–27
Stress-wave emissions
use in detecting incipient failures in pressure vessels, 4–17
Symposia
(see also Conferences and meetings and Seminars)
on instruments and techniques for the assessment of airborne radioactivity in nuclear operations, 54–62
on operating and developmental experience in the treatment of airborne radioactive wastes, 316–24
on packaging and transportation of radioactive materials, 415–25

T

Tantalum
compatibility with $(U,Pu)O_2$, 385–86
Thompson, Theos J.
appointment to the AEC, 464
planned speech at ORNL Nuclear Safety Program, 564
Thyroid
radiological-dose calculations from reactor accidents, survey of computer programs for, 513–20
Titanium
compatibility with $(U,Pu)O_2$, 384–85
Titanium alloys (Ti–V)
compatibility with $(U,Pu)O_2$, 386
Training
of reactor operators with computerized simulators, 405–10
of reactor operators in local meteorology, 431–36
Training courses
fast nuclear power-reactor safety at MIT, 209
UKAEA Reactor Safety Course No. 8, 118
UKAEA Reactor Safety Course No. 10, 564
water-cooled power-reactor safety at MIT, 209
Transportation
of radioactive materials, regulations for, 329–36
Transuranium elements
in-vivo counting in the human lung, 426–29
Tungsten
compatibility with $(U,Pu)O_2$, 386
Tungsten alloys (Re–W)
compatibility with $(U,Pu)O_2$, 386

U

United Kingdom
environmental monitoring, 504–12
reactor safety course No. 8, 118
reactor safety course No. 10, 564
United States
reactor-siting policies, comparison with Canada, 365–71

Uranium-235
misplacement occurrence at University of Florida Research Reactor, 343
Uranium mines
radiation exposure level in, regulations on, 272
Uranium oxide (UO_2)
fission-gas behavior in irradiated, 210–15
reaction with high-temperature steam, 396
Uranium oxide (UO_2)–stainless steel aerosols
removal from gas streams by filtration, effect of heat and moisture on, 321
Uranium oxide (UO_2)(stainless steel clad)
reaction with high-temperature steam, 396–97
Uranium oxide (UO_2)(Zircaloy clad)
reaction with high-temperature steam, 392–96
Uranium oxide systems ($(U,Pu)O_2$)
irradiation performance with various claddings, 380–89

V

Vanadium
compatibility with $(U,Pu)O_2$, 384–85
Vanadium alloys (Ti–V)
compatibility with $(U,Pu)O_2$, 386

W

Water
reaction with metals during light-water-cooled reactor accidents, 392–402
Workshop
on nuclear core-analysis techniques and criteria, 482

X

Xenon
removal from gas streams by adsorption in fluorocarbon solvents, 321
removal from gas streams by permselective membranes, 321
separation from Kr by F_2 reaction, 321

Y

Y-12 Plant, Oak Ridge, Tennessee
air cleaning activities, 323

Z

Zircaloy
reaction with high-temperature steam, 392–96
Zirconium
compatibility with $(U,Pu)O_2$, 384–85
reaction with high-temperature steam, 392–96

LEGAL NOTICE

This journal was prepared under the sponsorship of the U. S. Atomic Energy Commission. Neither the United States, nor the Commission, nor any person acting on behalf of the Commission:

A. Makes any warranty or representation, expressed or implied, with respect to the accuracy, completeness, or usefulness of the information contained in this journal, or that the use of any information, apparatus, method, or process disclosed in this journal may not infringe privately owned rights; or

B. Assumes any liabilities with respect to the use of, or for damages resulting from the use of any information, apparatus, method, or process disclosed in this journal.

As used in the above, "person acting on behalf of the Commission" includes any employee or contractor of the Commission, or employee of such contractor, to the extent that such employee or contractor of the Commission, or employee of such contractor prepares, disseminates, or provides access to, any information pursuant to his employment or contract with the Commission, or his employment with such contractor.